



Date: Oct. 30th 2020

Storage recommendation for Brake Chambers of *TSE Brakes*

TSE Brakes advises to not store Brake Chamber Products longer than the following time frame without actuation/cycling:

- Service-Chambers 3 Years
- Double-Diaphragm-Chambers 2 Years
- Clamp Units need additionally to be retightened after 6 Month of storage without actuation

For all longer storage without actuation/cycling TSE cannot assure a negative impact on the performance or the lifetime of the Product.

To maintain a functioning Product during this time of storage a dry environment is necessary.

Don't store the product outside unsheltered and don't get the stored packages wet so the Product soaks in moisture.

Further don't store the delivered Cardboard Boxes higher than 2 layers otherwise the weight of over 1.5t can damage the products.

Steel-Transportation-Racks can be stored up to 4 layers high depending on the local warehouse safety regulations.

Alexander Schmitt
Vice President of global Operations

TSE Brakes GmbH Hessenring 23 64546 Mörfelden-Walldorf, DE vertreten durch die Geschäftsführer
Valarie Burden, Alexander Schmitt und Jean Gregoire 94864 Handelsregister Darmstadt
Tel: +49 6105 3076650 www.TSEBrakes.com



A Marmon | Berkshire Hathaway Company